#### M. A. CECIL & ASSOCIATES, INC.

June 17, 2010

4475 SHANNON WAY, PORT REPUBLIC, MARYLAND 20676 (301) 855-7710 INDUSTRIAL HYGIENE AND ENVIRONMENTAL HEALTH

Ms. Lynn Zarate Montgomery County Public Schools 16651 Crabbs Branch Way Rockville, Maryland 20855

Re: Lead Based-Paint Assessment - Poolesville High School

Dear Ms. Zarate:

On June 4, 2010, M. A. Cecil and Associates, Inc., conducted a lead-based paint assessment at Poolesville High School. The scope of the lead-based paint (LBP) inspection included accessible interior and exterior surfaces of the building. The school is scheduled for demolition.

Non-destructive sampling methods were utilized. The lead based paint (LBP) inspection was conducted with a RMD x-ray fluorescence (XRF) analyzer. This instrument uses gamma radiation from a Cobalt-57 radioisotope source to determine the concentration of lead in surfaces analyzed. Generally, the testing was conducted in accordance with the Department of Housing and Urban Development (HUD), Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing. Paint with a lead concentration equal to or greater than 1.0 mg/cm² is considered lead-based paint. Multiple tests were conducted on each test combination (painted surface).

Generally, the classrooms and hallways were constructed with the same materials including white block walls, drywall and metal door jams. Each classroom was inspected and painted surfaces evaluated. The attached table contains a representative summary of the XRF results (classrooms). Lead base paint was not detected indoors or on exterior painted surfaces. The sampling results are summarized in the attached table.

Please note that in many of the hallways, classrooms, and in the original gym, tan, glazed brick/block was used for wall construction. The XRF evaluation indicates that the block glazing, more than likely, contains lead.

Should you have any questions concerning this matter please do not he sitate to contact this office at (703) 721-0400 or (301) 855-7710.

Sincerely,

Kim Fowler

Industrial Hygienist

Michael A. Cecil, CIH

RECEIVED

IUL - 6 2010

ENVIRONMENTAL SERVICE/IAQ

Table 1 XRF Results Poolesville High School June 4, 2010

Location	Description	Lead Based Paint	Reading	Condition
	off-white block wall	Negative	(-)0.1	Good
		Negative	0.0	Good
		Negative	0.0(-)	Good
		Negative	0.0	Good
	off-white brick	Negative	0.0	Good
		Negative	(-)0.0	Good
		Negative	0.2	Good
	Brown door jams	Negative	(-)0.1	Good
Class room 26		Negative	0.0	Good
Class 100111 20		Negative	0.2	Good
	Off-white drywall	Negative	0.1	Good
		Negative	0.1	Good
		Negative	0.2	Good
	Black door jam	Negative	0.1	Good
		Negative	0.1	Good
		Negative	0.1	Good
	White block wall	Negative	0.1	Good
		Negative	(-)0.0	Good
	2.4	Negative	0.0	Good
	Black lockers	Negative	0.1	Good
	· · ·	Negative	0.0	Good
		Positive	2.1	Good
	Tan brick	Positive	2.4	Good
	,	Positive	2.4	Good
77.11		Negative	0.3	Good
Hallways	White block walls	Negative	0.2	Good
		Negative	0.3	Good
	White drywall	Negative	0.3	Good
		Negative	0.2	Good
		Negative	0.3	Good
	Tan Brick (2 <sup>nd</sup> trial)	Positive	3.1	Good
		Positive	2.1	Good
		Positive	2.4	Good
	Orange lockers	Negative	0.6	Good
		Negative	0.3	Good
		Negative	0.2	Good
D 11.11 0 1	Black door/door jams	Negative	0.2	Good
Building Services		Negative	0.1	Good
Office		Negative	0.0	Good
		Negative	(-)0.0	Good
	White block wall	Negative	0.2	Good
		Negative	0.1	Good

Location	Description	Lead Based Paint	Reading	Condition
		Inc		some chipping
	Brown door jams	Inc		some chipping
		Inc		some chipping
		Negative	(-)0.1	Good
Class room 24	White block wall	Negative	0.0	Good
		Negative	0.2	Good
	White drywall	Negative	0.2	Good
		Negative	(-)0.2	Good
		Negative	0.0	Good
		Negative	0.1	Good
	White block wall	Negative	0.0	Good
C()		Negative	0.3	Good
Gym (new)		Negative	0.0	Good
	Black door/door jam	Negative	0.1	Good
		Negative	0.0	Good
Exterior door		Negative	0.3	Good
adjacent to	Black door/door jams	Negative	0.5	Good
Classroom 20		Negative	0.3	Good
	White block wall	Negative	0.1	Good
		Negative	0.0	Good
		Negative	0.1	Good
		Negative	0.0	Good
	Black door jams	Negative	0.1	Good
200		Negative	0.1	Good
Main office		Negative	(-)0.2	Good
	White drywall	Negative	(-)0.0	Good
		Negative	(-)0.1	Good
	Black window frames	Negative	0.0	Good
		Negative	0.0	Good
		Negative	0.1	Good
	Black door/door jams	Negative	0.0	Good
		Negative	0.1	Good
		Negative	(-)0.0	Good
Restrooms adjacent	Tan brick (trial 3)	Positive	6.3	Good
to Guidance		Positive	5.1	Good
Counselor's office		Positive	4.2	Good
Counselor's office	Green floor tiles	Negative	0.1	Good
		Negative	0.0	Good
		Negative	0.0	Good

Location	Description	Lead Based Paint	Reading	Condition
Junior High Gym		Positive	3.2	Good
	Tan brick (trial 4)	Positive	2.4	Good
		Positive	4.1	Good
		Negative	0.1	Good
	White block wall	Negative	0.1	Good
(original)		Negative	(-)0.0	Good
	Black door/door jams	Negative	0.1	Good
		Negative	0.0	Good
		Negative	0.3	Good
Exterior doors	9	Negative	(-)0.2	Good
adjacent to	Black door/door jams	Negative	(-)0.1	Good
classroom 8		Negative	0.2	Good
		Negative	0.1	Good
	White block wall	Negative	0.0	Good
		Negative	0.1	Good
		Negative	(-)0.0	Good
	White drywall	Negative	0.3	Good
C1 0		Negative	(-)0.0	Good
Class room 8		Negative	0.1	Good
	Brown door jam	Negative	0.0	Good
		Negative	0.1	Good
	D1 1 11 1	Negative	0.3	Good
	Blue base tile around perimeter	Negative	0.1	Good
		Negative	0.0	Good
	White block wall	Negative	0.0	Good
		Negative	0.1	Good
		Negative	(-)0.1	Good
Security Office	Black door/door jam	Negative	0.2	Good
		Negative	0.3	Good
		Negative	0.1	Good
D	Tan brick (trial 5)	Positive	3.4	Good
Restrooms across		Positive	4.1	Good
from Career Center		Positive	2.7	Good
	Tan brick (trial 6)	Positive	3.2	Good
		Positive	3.2	Good
		Positive	2.4	Good
Cafeteria	White block wall	Negative	0.2	Good
		Negative	(-)0.0	Good
		Negative	(-)0.1	Good

Location	Description	Lead Based Paint	Reading	Condition
		Negative	(-)0.2	Good
	White brick	Negative	0.1	Good
		Negative	0.2	Good
		Negative	(-)0.1	Good
	White block wall	Negative	0.0	Good
Class room 35		Negative	0.0	Good
Class room 33	White drywall	Negative	0.3	Good
		Negative	0.3	Good
		Negative	0.2	Good
		Negative	0.0	Good
	Black door jam	Negative	(-)0.0	Good
		Negative	0.1	Good
		Negative	0.1	Good
	White block wall	Negative	0.1	Good
Class 45 54 27		Negative	(-)0.1	Good
Class room 37		Negative	(-)0.1	Good
	Gray door jam	Negative	0.1	Good
		Negative	0.0	Good
		Negative	0.0	Good
	White block wall	Negative	0.1	Good
		Negative	(-)0.1	Good
		Negative	0.0	Good
Class room 36	Blue block wall	Negative	0.1	Good
		Negative	(-)0.0	Good
	0 1	Negative	(-)0.2	Good
	Grey door	Negative	0.0	Good
	jam/window frame	Negative	0.1	Good
		Negative	0.0	Good
	White block wall	Negative	0.1	Good
G1 40	White block wall	Negative	(-)0.1	Good
Class room 42	Grey door jam	Negative	0.0	Good
		Negative	0.1	Good
		Negative	0.2	Good
	White block wall	Negative	(-)0.0	Good
		Negative	(-)0.1	Good
DAC		Negative	(-)0.1	Good
IMC	Grey door jams	Negative	0.4	Good
		Negative	0.2	Good
		Negative	0.0	Good
D 11	Tan ceramic wall tile	Negative	(-)0.1	Good
Restrooms adjacent		Negative	0.0	Good
to IMC		Negative	0.1	Good
		Negative	0.0	Good
Art Room	Red door jams/window frames	Negative	0.1	Good
		Negative	(-)0.1	Good

Location	Description	Lead Based Paint	Reading	Condition
		Negative	0.0	Good
Staff Rest Rooms	Orange ceramic wall tile	Negative	0.1	Good
	tile	Negative	(-)0.2	Good
DI 1 15:		Positive	4.4	Good
Physical Education	Tan brick (trial 7)	Positive	2.5	Good
hallway		Positive	2.9	Good
	Tan brick (trial 8)	Positive	3.3	Good
		Positive	5.2	Good
D		Positive	2.4	Good
Boy's Locker Room		Negative	0.1	Good
	Blue block wall	Negative	(-)0.1	Good
		Negative	0.0	Good
		Positive	3.2	Good
	Tan brick (trial 9)	Positive	3.6	Good
C' 1) I I D		Positive	2.4	Good
Girl's Locker Room	Blue/Gray block wall	Negative	(-)0.1	Good
		Negative	0.0	Good
		Negative	0.2	Good
		Negative	0.0	Good
Career Center	Grey stairs	Negative	0.1	Good
		Negative	0.1	Good
		Negative	0.3	Good
	Blue brick	Negative	0.4	Good
		Negative	0.2	Good
		Negative	(-)0.0	Good
	Blue block wall	Negative	0.1	Good
D '1 D		Negative	0.1	Good
Boiler Room	Grey floor	Negative	0.2	Good
		Negative	0.3	Good
		Negative	0.1	Good
		Negative	0.3	Good
	Grey steps	Negative	0.2	Good
		Negative	0.1	Good
	Brown doors/door jam	Negative	0.2	Good
Main entrance		Negative	0.1	Good
		Negative	(-)0.1	Good
	D	Negative	0.3	Chipped
Roof of old Gym	Brown painted window frames	Negative	0.1	Chipped
,		Negative	0.4	Chipped