
Piney Branch ES FEASIBILITY STUDY

Community Meeting 4 JUNE 4, 2025
























Welcome Virtual Attendes

...we're glad you're here!

Piney Branch Team



Montgomery County Public Schools

Main Point of Contact



Julie Morris

DIVISION OF DESIGN + CONSTRUCTION

Director,
Division of Planning, Design
and Construction



Robbie Badstibner

DIVISION OF DESIGN +
CONSTRUCTION

School Facilities, Project Manager



Erika Dworkin

DIVISION OF CAPITAL
PLANNING AND REAL ESTATE
School Facilities, Planner II



Jasmin McDuffie

AIA, NCARB, LEED AP

Principal-in-Charge



Stantec Architecture

Bill Bradley

PHD, AIA, LEED AP, ALEP

Educational Planner



Carolyn Frederick

AIA, LEED AP BD+C

Sr. Project Architect

Robbie_s_badstibner@mcpsmd.org 240-367-0913

Piney Branch Team



Civil, Building Systems Engineers, Pool Specialist, and Cost Estimators











Sean Lindaman

PΕ

Civil



Structural Engineer

Mechanical, Electrical, Plumbing, Fire Protection





Professional Cost **Estimator**
















Agenda


- 1. Why We Are Here
- 2. Schedule
- 3. Observations + Feedback
- 4. Design Options
- 5. Discussion

*The boundary study will not be discussed during this meeting





Why We Are Here





Why We Are Here

Overall

To complete a feasibility study to determine the most effective, efficient, and affordable ways to improve

- safety and security,
- instruction and delivery,
- occupant health and well being,
- site and building accessibility, and
- operational efficiency and effectiveness.

To help inform the Superintendent's Fall 2025 CIP.

Tonight

To share options for addressing issues identified at Piney Branch with interested community members.

To solicit input from community members on the options.



Schedule

Schedule



○ 1. April 23: City of Takoma Park meeting

2. May 1: Community meeting #1

3. May 13: Community (staff) meeting

4. May 15: Community meeting #2

5. May 29: Community meeting #3

O 6. June 4: Community meeting #4


O 7. July 23: City of Takoma Park meeting / presentation

O 8. TBD: Additional community meeting, holding center discussion

Looking Forward

July: Feasibility Study to be sent to Superintendent for review

October: Superintendent to make recommendation to the Board of Education







Observations + Feedback


Issues to be Addressed








- Safer Pedestrian Site Circulation
- Safer Drop-off / Pick-up
- More Secure Entrance
- More Parking / Accessible Parking
- Accessible Access to Playground
- Accessible Access Throughout
- Clear Circulation Inside School
- Natural Light in All Classrooms
- Upgrade Classrooms Per Ed Spec
- Library as Heart of the School
- More Efficient Mechanical Systems
- Fix Leaky Pipes / Roof
- Upgrades Per Code / Regulations
- Replace Windows / Doors / Roof
- Update Pool Equipment
- Continued Community Access to Pool





Looking at the Existing Plan










Existing Site Considerations





Existing Parking Count





Existing Parking


- **44** spots on site
- Additional spots on Maple Ave

Ed Spec Parking Requirement

- 80 required spots with a 10% acceptable variation (72-88 spots)
- Currently 45% below requirement







Design Options

Design Options



1.




RENOVATION

Code Compliance Spec Compliance Systems Upgrades Security Upgrades

1a. With Pool


1b. Without Pool

2.



RENOVATION
SMALL DEMO
SMALL ADDITION

Code Compliance Spec Compliance Systems Upgrades Security Upgrades 3.




RENOVATION
LARGE DEMO
LARGE ADDITION

Code Compliance Spec Compliance Systems Upgrades Security Upgrades

3a. With Pool

4.



NO RENO
COMPLETE DEMO
NEW SCHOOL

Code Compliance Spec Compliance Systems Upgrades Security Upgrades

4a. With Pool

4b. Without Pool

2b. Without Pool

3b. Without Pool

Existing Building





Design Options




1.



Code Compliance Spec Compliance Systems Upgrades Security Upgrades


1a. With Pool





1a: Renovate Existing Building with pool





1a: Renovate Existing Building with pool





1a: Typical Classroom Floor Plan





- Safer Drop-off / Pick-up
- Safer Pedestrian Site Circulation
- More Parking / Accessible Parking
- More Secure Entrance
- Accessible Access to Playground
- Accessible Access Throughout
- Clear Circulation Inside School
- Natural Light in *All* Classrooms
- Upgrade Classrooms Per Ed Spec
- Library as Heart of the School
- Install Efficient Building Systems
- Repair Leaky Pipes
- Upgrades Per Code / Regulations
- Replace Windows / Doors / Roof
- Maintain Access to a Pool
- Update Pool Equipment



1a: Renovate Existing Building with pool



Piney Branch Elementary School Program Comparison

Zone / Areas	Ed Spec	Option 1A (Pool)	Variance (%)
Classrooms	27,650	25,178	-10%▼
Support Rooms	2,420	2,553	5% _K
Library Media Center	2,875	2,831	-2%▼
Physical Education*	4,430	5,670	22%▲
Multi-Purpose Room*	4,135	4,087	-1%▼
Kitchen*	1,372	2,825	51%▲
Administration	1,765	1,765	0%▲
Counseling Suite	320	350	9%▲
Staff Development Area	600	650	8%▲
Health Services Suite	710	750	5%▲
Staff Areas	750	744	-1%▼
Building Support Factilities	1,885	1,936	3%▲
Building Support Areas	600	600	0%▲
Pool**	0	8,869	100%▲
Total Proposed (NSF) =	49,512		
Total Options =		58,808	
Variance (%)=		18.78%	
Total Buidling Gross SF (BGSF) =	102,461	102,461	

Summary Findings

- Existing building constraints don't allow for right sizing of program
- Still contending with split level and accessibility / supervision challenges



^{*}When utilizing the existing footprint of the gym/multi-purpose/platform/kitchen (shown with BOLD text). Existing footprint is oversized compared to the proposed program.

^{**} Existing pool footprint is being maintained (shown with BOLD text). Pool scope is not part of proposed program.

Design Options



1.




Code Compliance Spec Compliance Systems Upgrades Security Upgrades

1b. Without Pool

1b: Renovate Existing Building without pool





BRANCH ES FEASIBILITY STUDY

1b: Renovate Existing Building without pool





1b: Level 1





1b: Level 2 & 3





1b: Level 4





- Safer Drop-off / Pick-up
- Safer Pedestrian Site Circulation
- More Parking / Accessible Parking
- More Secure Entrance
- Accessible Access to Playground
- Accessible Access Throughout
- Clear Circulation Inside School
- Natural Light in *All* Classrooms
- Upgrade Classrooms Per Ed Spec
- Library as Heart of the School
- Install Efficient Building Systems
- Repair Leaky Pipes
- Upgrades Per Code / Regulations
- Replace Windows / Doors / Roof
- Maintain Access to a Pool
- Update Pool Equipment



1b: Renovate Existing Building without pool



Piney Branch Elementary School Program Comparison

Zone / Areas	Ed Spec	Option 1B (No Pool)	Variance
Classrooms	27,650	26,872	-3%▼
Support Rooms	2,420	2,525	4%▲
Library Media Center	2,875	2,831	-2%▼
Physical Education*	4,430	5,872	25%▲
Multi-Purpose Room*	4,135	4,784	14%▲
Kitchen*	1,372	1,380	1%▲
Administration	1,765	1,765	0%▲
Counseling Suite	320	350	9%▲
Staff Development Area	600	660	9%▲
Health Services Suite	710	780	9%▲
Staff Areas	750	763	2%▲
Building Support Factilities	1,885	2,516	25%▲
Building Support Areas	600	760	21%▲
Pool**	0	0	-
Total Proposed (NSF) =	49,512		
Total Options =	,312	51,858	
Variance (%)=		4.74%	
Total Buidling Gross SF (BGSF) =	102,461	102,461	

Summary Findings

- With no pool multipurpose room can be right sized & the music/art suite can be adjacent
- Still contending with split level and accessibility / supervision challenges




^{*}When utilizing the existing footprint of the gym/multi-purpose/platform/kitchen (shown with BOLD text). Existing footprint is oversized compared to the proposed program.

^{**} Existing pool footprint is being maintained (shown with BOLD text). Pool scope is not part of proposed program.

Design Options



2,




RENOVATION
SMALL DEMO
SMALL ADDITION

Code Compliance Spec Compliance Systems Upgrades Security Upgrades

2b. Without Pool


2b: Renovate + Smaller Addition without pool





2b: Renovate + Smaller Addition without pool






BRANCH ES FEASIBILITY STUDY

2b: Renovate + Smaller Addition without pool





2b: Level 1





2b: Level 2









- Safer Drop-off / Pick-up
- Safer Pedestrian Site Circulation
- More Parking / Accessible Parking
- More Secure Entrance
- Accessible Access to Playground
- Accessible Access Throughout
- Clear Circulation Inside School
- Natural Light in *All* Classrooms
- Upgrade Classrooms Per Ed Spec
- Library as Heart of the School
- Install Efficient Building Systems
- Repair Leaky Pipes
- Upgrades Per Code / Regulations
- Replace Windows / Doors / Roof
- Maintain Access to a Pool
- Update Pool Equipment



2b: Renovate + Smaller Addition without pool



Piney Branch Elementary School Program Comparison

Zone / Areas	Ed Spec	Option 2B (No Pool)	Variance (%)
Classrooms	27,650	28,444	3%▲
Support Rooms	2,420	2,536	5%▲
Library Media Center	2,875	3,262	12%▲
Physical Education*	4,430	5,350	17%▲
Multi-Purpose Room*	4,135	4,596	10%▲
Kitchen*	1,372	1,380	1%▲
Administration	1,765	1,828	3%▲
Counseling Suite	320	350	9%▲
Staff Development Area	600	650	8%▲
Health Services Suite	710	750	5%▲
Staff Areas	750	800	6%▲
Building Support Factilities	1,885	3,134	40%▲
Building Support Areas	600	723	17%▲
Pool**	0	0	-
Total Proposed (NSF) =	49,512		
Total Options =		53,803	
Variance (%)=		8.67%	
Total Buidling Gross SF (BGSF) =	102,461	-	

Summary Findings

- The split level is removed, and the library becomes easily accessible on Levels 1, 2, & 3
- Restrooms are stacked on Level's 2 & 3 and easily supervised





Level 1

Level 2



Level 3


^{*}When utilizing the existing footprint of the gym/multi-purpose/platform/kitchen (shown with BOLD text). Existing footprint is oversized compared to the proposed program.

^{**} Existing pool footprint is being maintained (shown with BOLD text). Pool scope is not part of proposed program.

Design Options



3.



RENOVATION
LARGE DEMO
LARGE ADDITION

Code Compliance Spec Compliance Systems Upgrades Security Upgrades

3a. With Pool

3a: Renovate + Larger Addition with pool











PINEY BRANCH ES FEASIBILITY STUDY





- Safer Drop-off / Pick-up
- Safer Pedestrian Site Circulation
- More Parking / Accessible Parking
- More Secure Entrance
- Accessible Access to Playground
- Accessible Access Throughout
- Clear Circulation Inside School
- Natural Light in *All* Classrooms
- Upgrade Classrooms Per Ed Spec
- Library as Heart of the School
- Install Efficient Building Systems
- Repair Leaky Pipes
- Upgrades Per Code / Regulations
- Replace Windows / Doors / Roof
- Maintain Access to a Pool
- Update Pool Equipment



3a: Renovate + Larger Addition with pool




Piney Branch Elementary School Program Comparison

Zone / Areas	Ed Spec	Option 3A (Pool)	Variance (%)
Classrooms	27,650	28,600	3%▲
Support Rooms	2,420	2,480	2%▲
Library Media Center	2,875	3,175	9%▲
Physical Education*	4,430	6,226	29%▲
Multi-Purpose Room*	4,135	4,301	4%▲
Kitchen*	1,372	1,437	5%▲
Administration	1,765	1,883	6%▲
Counseling Suite	320	320	0%▲
Staff Development Area	600	600	0%▲
Health Services Suite	710	710	0%▲
Staff Areas	750	750	0%▲
Building Support Factilities	1,885	1,885	0%▲
Building Support Areas	600	600	0%▲
Pool**	0	8,291	100%▲
Total Proposed (NSF) =	49,512		
Total Options =		61,258	
Variance (%)=		23.72%	
Total Buidling Gross SF (BGSF) =	102,461	98,622	


Summary Findings

- Gross SF variance is driven by large mechanical spaces serving existing pool & gym at level 2
- 65 parking spots (48% increase)





Level 1



Level 2



Level 3 Level 4


^{*}When utilizing the existing footprint of the gym/multi-purpose/platform/kitchen (shown with BOLD text). Existing footprint is oversized compared to the proposed program.

^{**} Existing pool footprint is being maintained (shown with BOLD text). Pool scope is not part of proposed program.

Design Options



3.



RENOVATION
LARGE DEMO
LARGE ADDITION

Code Compliance Spec Compliance Systems Upgrades Security Upgrades

3b. Without Pool

3b: Renovate + Larger Addition without pool

















- Safer Drop-off / Pick-up
- Safer Pedestrian Site Circulation
- More Parking / Accessible Parking
- More Secure Entrance
- Accessible Access to Playground
- Accessible Access Throughout
- Clear Circulation Inside School
- Natural Light in *All* Classrooms
- Upgrade Classrooms Per Ed Spec
- Library as Heart of the School
- Install Efficient Building Systems
- Repair Leaky Pipes
- Upgrades Per Code / Regulations
- Replace Windows / Doors / Roof
- Maintain Access to a Pool
- Update Pool Equipment



3b: Renovate + Larger Addition without pool




Piney Branch Elementary School Program Comparison

Zone / Areas	Ed Spec	Option 3B (No Pool)	Variance (%)
Classrooms	27,650	28,662	4%▲
Support Rooms	2,420	2,400	-1%▼
Library Media Center	2,875	2,865	-0%▼
Physical Education*	4,430	6,642	33%▲
Multi-Purpose Room*	4,135	4,343	5%▲
Kitchen*	1,372	1,350	-2%▼
Administration	1,765	1,765	0%▲
Counseling Suite	320	320	0%▲
Staff Development Area	600	600	0%▲
Health Services Suite	710	710	0%▲
Staff Areas	750	750	0%▲
Building Support Factilities	1,885	1,885	0%▲
Building Support Areas	600	600	0%▲
Pool**	0	0	_
Total Proposed (NSF) =	49,512		
Total Options =		52,892	
Variance (%)=		6.83%	
Total Buidling Gross SF (BGSF) =	102,461	78,783	

Summary Findings

- The elimination of the pool allows for a 3 story scheme much closer to the ed spec square footages
- 80 parking spots (81% increase)







Level 2

Level 3


^{*}When utilizing the existing footprint of the gym/multi-purpose/platform/kitchen (shown with BOLD text). Existing footprint is oversized compared to the proposed program.

^{**} Existing pool footprint is being maintained (shown with BOLD text). Pool scope is not part of proposed program.

Design Options



4.



NO RENO
COMPLETE DEMO
NEW SCHOOL

Code Compliance Spec Compliance Systems Upgrades Security Upgrades

4a. With Pool

4a: Build New with pool




















- Safer Drop-off / Pick-up
- Safer Pedestrian Site Circulation
- More Parking / Accessible Parking
- More Secure Entrance
- Accessible Access to Playground
- Accessible Access Throughout
- Clear Circulation Inside School
- Natural Light in *All* Classrooms
- Classrooms Per Ed Spec
- Library as Heart of the School
- New Efficient Building Systems
- New Efficient Pipes
- Per Code / Regulations
- New Windows / Doors / Roof
- Maintain Access to a Pool
- Update Pool Equipment



4a: Build New with pool




Piney Branch Elementary School Program Comparison

Zone / Areas	Ed Spec	Option 4A (Pool)	Variance (%)
Classrooms	27,650	27,605	-0%▼
Support Rooms	2,420	2,423	0%▲
Library Media Center	2,875	2,734	-5%▼
Physical Education*	4,430	4,445	0%▲
Multi-Purpose Room*	4,135	4,462	7%▲
Kitchen*	1,372	1,372	0%▲
Administration	1,765	1,777	1%▲
Counseling Suite	320	320	0%▲
Staff Development Area	600	600	0%▲
Health Services Suite	710	710	0%▲
Staff Areas	750	750	0%▲
Building Support Factilities	1,885	1,887	0%▲
Building Support Areas	600	680	12%▲
Pool**	0	7,452	100%▲
Total Proposed (NSF) =	49,512		
Total Options =		57,217	
Variance (%)=		15.56%	
Total Buidling Gross SF (BGSF) =	102,461	80,743	

Summary Findings

- Right sized program
- Entrance off Grant Ave with generous public plaza
- 58 parking spots (32% increase)




^{*}When utilizing the existing footprint of the gym/multi-purpose/platform/kitchen (shown with BOLD text). Existing footprint is oversized compared to the proposed program.

^{**} Existing pool footprint is being maintained (shown with BOLD text). Pool scope is not part of proposed program.

Design Options



4.



NO RENO
COMPLETE DEMO
NEW SCHOOL

Code Compliance Spec Compliance Systems Upgrades Security Upgrades


4b. Without Pool

4b: Build New without pool





















- Safer Drop-off / Pick-up
- Safer Pedestrian Site Circulation
- More Parking / Accessible Parking
- More Secure Entrance
- Accessible Access to Playground
- Accessible Access Throughout
- Clear Circulation Inside School
- Natural Light in *All* Classrooms
- Classrooms Per Ed Spec
- Library as Heart of the School
- New Efficient Building Systems
- New Efficient Pipes
- Per Code / Regulations
- New Windows / Doors / Roof
- Maintain Access to a Pool
- Update Pool Equipment



4b: Build New without pool



Piney Branch Elementary School Program Comparison

Zone / Areas	Ed Spec	Option 4B (No Pool)	Variance (%)
Classrooms	27,650	27,611	-0%▼
Support Rooms	2,420	2,460	2%▲
Library Media Center	2,875	2,852	-1%▼
Physical Education*	4,430	4,778	7%▲
Multi-Purpose Room*	4,135	4,142	0%▲
Kitchen*	1,372	1,406	2%▲
Administration	1,765	1,770	0%▲
Counseling Suite	320	325	2%▲
Staff Development Area	600	600	0%▲
Health Services Suite	710	725	2%▲
Staff Areas	750	750	0%▲
Building Support Factilities	1,885	1,954	4%▲
Building Support Areas	600	680	12%▲
Pool**	0	0	-
Total Proposed (NSF) =	49,512		
Total Options =		50,053	
Variance (%)=		1.09%	
Total Buidling Gross SF (BGSF) =	102,461	69,384	

Summary Findings

- Right sized program
- 72 parking spots (64 % increase)



^{*}When utilizing the existing footprint of the gym/multi-purpose/platform/kitchen (shown with BOLD text). Existing footprint is oversized compared to the proposed program.

^{**} Existing pool footprint is being maintained (shown with BOLD text). Pool scope is not part of proposed program.

Questions



- 1. How effectively (1-10) does this solution serve the community? Why?
- 2. How effectively (1-10) does this solution serve teachers and students? Why?





RENOVATION

1a. With Pool

1b. Without Pool



RENOVATION
SMALL DEMO
SMALL ADDITION

2a. N/A **2b.** Without Pool





RENOVATION
LARGE DEMO
LARGE ADDITION

3a. With Pool **3b.** Without Pool





NO RENO
COMPLETE DEMO
NEW SCHOOL

4a. With Pool **4b.** Without Pool

